






COMPONENT SIDE		2 LAYER
	SM721FA0-1V0	2025-01-21
Clearance CK	False Error	00106
Connectivity CK	False Error	00000
Plane Check	False Error	00000
1		



SOLDER SIDE		2 LAYER
	SM721FA0-1V0	2025-01-21
Clearance CK	False Error	00106
Connectivity CK	False Error	00000
Plane Check	False Error	00000
2		



COMPONENT SIDE		2 LAYER	
	SM721FA0-1V0	2025-01-21	
Clearance CK	False Error	00106	
Connectivity CK	False Error	00000	
Plane Check	False Error	00000	
12			